
KONZER

SIZE CHART


K2000 / PROTECTIVE COVERALL

GARMENT MEASUREMENTS

Unit: cm | Tolerance: ±2 cm



FRONT



BACK

Lettered arrows correspond to the table below. Diagrams are schematic.

MEASUREMENT	S	M	L	XL	XXL	XXXL	XXXXL	XXXXXL
A **Body length** — Shoulder / neck seam to hem	161	165	170	178	186	187	190	192
B **Total length** — Top of hood to hem	188	192	199	207	215	216	220	222
Chest — Flat width · one side	61	62	64.5	67	70	73	75	78
C **Sleeve length** — From centre back to cuff	88	88.5	89.5	91	95	95	97	99
D **Inside leg** — Crotch to hem	82	83	84	85	87.5	87.5	88	89
Hood height / width	34 / 26	34 / 26	34 / 26	34 / 26	34 / 26	34 / 26	34 / 26	34 / 26
Cuff opening — Relaxed	8–9	8–9	8–9	8–9	8–9	8–9	8–9	8–9
Leg opening — Relaxed	12–13	12–13	12–13	12–13	13–14	13–14	13–14	13–14
Face opening — Relaxed	17–18	17–18	17–18	17–18	17–18	17–18	17–18	17–18
Half waist — Relaxed	31	33	33	35	37	37	37	37
Measurement tolerance	±2	±2	±2	±2	±2	±2	±2	±2

These are finished-garment dimensions, not body measurements or recommended wearer heights.

Chest is measured flat across one side of the garment. Openings and half waist are measured relaxed.

All measurements are in centimetres. Measurement tolerance: ±2 cm.